




McElroy Manufacturing, Inc.
 The leader by design.
 Tulsa, Oklahoma U.S.A.

DRAWN: RWH	CHECK: ERA	APPRV'D: BWJ	DATE: 3/20/17	SHT No: 1	REV No: G	PART No: T1831901
------------	------------	--------------	---------------	-----------	-----------	-------------------

GENERATOR MODIFICATION

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

- NOTES:
 1. ALIGN BOTTOM EDGE OF ITEM 11 FUSE BLOCK WITH BOTTOM EDGE OF ITEM 12 MOUNTING PLATE TO INSURE CLEARANCE FOR COVER.



McElroy Manufacturing Parts List

Part Number: T1831901 Generator Modification



Generator mod

Part Number T1831901 Component List

Item	Component	Description	Quantity	Unit	Price
F1	MLQ00055	20 Amp Fuse (Effective to 1/26/20)	1.0	EA	21.52
F1	MLQ00057	20 Amp Fuse	1.0	EA	40.69
F2	MLQ00055	20 Amp Fuse (Effective to 1/26/20)	1.0	EA	21.52
F2	MLQ00057	20 Amp Fuse	1.0	EA	40.69
SPA RE	MLQ00055	20 Amp Fuse (Effective to 1/26/20)	2.0	EA	21.52
SPA RE	MLQ00057	20 Amp Fuse (Effective 1/27/20 to 6/17/20)	2.0	EA	40.69
1	MAH00153	#10-24NCX3/8LG Rhpm	2.0	EA	0.99
2	MAL00023	1/4-20NC X 1/2LG Hwh TF Screw	2.0	EA	0.00
2	MAC00051	1/4-20NCX1/2LG Shcs PL (Effective 8/30/18 to 2/24/19)	2.0	EA	0.34
3	MDC00081	6KW, 60HZ, 120/240V Alternator	1.0	EA	1,395.00
4	MLJ00049	1/2 X 90DEG Conduit Fitting (Effective to 12/7/17)	1.0	EA	17.96
5	MLL00189	#12 UL3173 Wire, Black	0.833	FT	1.07
6	MLL00190	#12 UL3173 Wire, Red	0.833	FT	1.07
7	MLL00191	#12 UL3173 Wire, Green	0.333	FT	1.07
8	MLM00008	10-12 X #10 Ring Terminal	3.0	EA	1.27
9	MLM00250	#12 X 10MM Insulated Ferrule (Effective to 8/15/17)	2.0	EA	1.36
9	MLM00340	10-12 X #10 Fork Terminal	3.0	EA	1.09
10	MLR00033	Spare Fuse Holder (Effective to 6/17/20)	1.0	EA	26.98
11	MLR00042	Non-rejection Fuse Block (Effective to 8/29/18)	1.0	EA	37.46
11	MLR00072	30A 2-POLE Class CC Fuse Block	1.0	EA	42.00
12	T1825301	Fuse Block Mount	1.0	EA	22.13

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.