


NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED TO OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.



McElroy Manufacturing Parts List

Part Number: A430101 PitBull 14 100-120v,50/60Hz,1Ph Fusion Machine Package

Part Number A430101 Component List

Item	Component	Description	Quantity	Unit	Price
1	430101	PitBull 14 Fusion Machine Assembly	1.0	EA	2,140.00
2	433701	PitBull 14 100-120V,50/60Hz,1Ph Facer Assembly	1.0	EA	2,463.00
3	433104	PitBull 14 Heater/Facer Stand Assembly	1.0	EA	435.00
4	A424313	PitBull 14 Butt Plate 100-120V, 50/60Hz, 1Ph Heater Kit (Effective 5/16/02 to 2/1/05)	1.0	EA	0.00
4	A424317	Obsolete & Replaced by 469801 (Effective 2/2/05 to 2/9/20)	1.0	EA	0.00
4	469801	PitBull® No. 14 butt plate 100-120v,50/60hz Heater Assembly	1.0	EA	862.00

Please visit <https://fusion.mcelroy.com/parts> to purchase parts or for more information.

